


### FACTS AND FIGURES



Damage Status - Private Structures

### MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	96.52%	90.24%
Reinforced Cement Concrete (RCC) Frame	1.22%	1.57%
Stone and Cement Mortar Masonry	1.04%	1.23%
Brick and Cement Mortar Masonry	0.40%	2.55%
Others	0.82%	4.41%

CBS damage assessment survey, 2015

### HOUSING RECONSTRUCTION & RETROFIT UPDATES

#### Reconstruction Status

Total Eligible HHs	4,591
PA Agreement	4,462 (129)
I <sup>st</sup> Tranche received	4,462 (129)
II <sup>nd</sup> Tranche received	4,299 (292)
III <sup>rd</sup> Tranche received	3,609 (982)

#### Houses

Under Construction: - Completed: -

#### Retrofitting Status

Total Eligible HHs	19
PA Agreement	5 (14)
I <sup>st</sup> Tranche received	5 (14)
II <sup>nd</sup> Tranche received	- (19)

#### Grievances

Registered: 930  
Addressed: 485

#### Non-compliances

Registered: -  
Addressed: -

Data Updated on: 2019-05-27 00:00:00

### PO Presence

Active: JICA (Shelter)

Phased Out: AATWIN (Social Protection), CFJ (Education), GON-PAF (Shelter), ICCO (Agriculture), ICCO (DRM), ICCO (Education), ICCO (Livelihood), ICCO (Shelter), JICA (Shelter), MC (Shelter), NRA (Shelter), OXFAM-GB (Shelter), PIN (DRM), PIN (Governance), PIN (Shelter), PLAN (Hygiene), Praramva (Education), SABAL (Shelter), SCI (Nutrition), SCI (Shelter)

### STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m <sup>3</sup>	101,425	Y	1,764
Aggregate	m <sup>3</sup>	98,610	Y	3,000
Sand	m <sup>3</sup>	10,783	Y	3,000
Timber	cu. ft.	12,271	N	-
Cement (PPC)	Sack	-	Y	847
Cement (OPC)	Sack	330,453	Y	949
Rebars	kgs.	1,111,430	Y	97
Tin	bundle	13,514	Y	11,200
Bricks	pcs.	1,834,218	Y	19

#### Types of Workers

1. Skilled mason
2. Labourer

#### Avg. daily wage (NRs.)

1,500 /-  
1,000 /-

### OTHER SECTORS



#### Schools

Damaged: 35  
Under Construction: 24  
Construction Completed: 24



#### Health Posts

Damaged: -  
Under Construction: -  
Construction Completed: -

### KEY CONTACTS

#### Municipal Office

Bhupendra Shrestha  
Chairman  
9851210270

#### Municipal Office

Sunil Shrestha  
Focal Person  
9849394426

#### Municipal Office

Durga Nepal  
Deputy Chairman  
9741181911

#### GMaLI/NRA

NRA Chief-District

#### Municipal Office

Rajendra Prasad Nepal  
Chief Administration Officer  
9841535479

#### DLPIU-Building

Santosh Kumar Niraula  
DUDBC.DLPIU Chief  
9851136372

## HHs WITH LAND ISSUES

No Reported Land Issues

## STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	6	6
Sub-Engineers	4	4
Asst. Sub-Engineers	5	6
Masons	- (7 days) - (50 days)	- (7 days) - (50 days)

Source: Municipal survey

## MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

## TA ACTIVITIES MAP



## FAQs

**Q: What documents are required for enrolment in the GoN housing reconstruction programme?**

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

**Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?**

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. (District Coordinator) 2. Pradip Sharma (District Technical Officer) 3. (District Information Management Officer)  
9851073208